

Oil Field Environmental Incident Summary

Incident: 20150818134821 **Date/Time of Notice:** 08/18/2015 13:48

Responsible Party: T & S TRANSPORTATION INC

Well Operator: THUNDERBIRD RESOURCES LP

Well Name: WATSON B N34-11-1H

Field Name: RANCH CREEK

Well File #: 25123

Date Incident: 8/17/2015 **Time Incident:** 08:45

Facility ID Number:

County: MCKENZIE

Twp: 146

Rng: 99

Sec: 11

Qtr:

Location Description:

Submitted By: Jessica Price

Received By:

Contact Person: Todd O'Donnell
12246 GOSS AVE
SIDNEY, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	1.4	Barrels	1.4	Barrels

Followup **Units**

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No.

Areal Extent:

Potential Environmental Impacts:

Soil was contaminated.

Action Taken or Planned:

Soil was hydro-vacced and then removed by loader and taken to disposal. New gravel was delivered to location.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/18/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill impacted areas on location. NDIC retains oversight.